



Traffic Management when machinery is on road.



Check power tools!
General condition, Safety guards & rmp rating
of cutting discs etc

Walking through work zone



Exclusion zones must be adhered to.





*Water hose initially under power board.
Entrance holes not capped or blocked.*

*Check temporary power boards – common issue
across many sites.*



No bunting - Ensure unsafe areas are appropriately secured.



Worker moving in strike zone of machinery: Establish clear exclusion zones

Housekeeping inside containers – generally a very poor standard observed.





Interiors of vehicles must be kept tidy.



Fuel cans must be clearly labelled