

Belair Road retaining walls maintenance works

Fact sheet – Vegetation management

We are undertaking maintenance works along Belair Road, below the Windy Point Lookout, Lynton. The works are required to preserve the long-term structural integrity of this section of Belair Road.

Tree and vegetation removal

We understand that trees are highly valued by the community. While every effort has been made to retain trees and vegetation, removals will be required to undertake these essential maintenance works and preserve the long-term structural integrity of Belair Road.

During the maintenance design process impacts on trees and vegetation has been minimised as much as possible.

The maintenance works will involve the removal of approximately 35 native trees (*Eucalyptus microcarpa* – “Grey Box”). Vegetation removals will be limited to areas directly impacted by the maintenance work required.

All vegetation impacts will be managed in accordance with legislative requirements and our Vegetation Impact Assessment Guideline (the Guideline).

Taking care during tree removal and pruning

Where impacts cannot be avoided, all care and consideration will be taken in the removal and handling of trees and vegetation.

All pruning and removal of vegetation will be carefully undertaken by a suitably qualified arborist.

Trees will be inspected prior to removal and if animals are found, they will be relocated by appropriately qualified professionals.

For more information

- Call: 1300 794 880
- Visit: dit.sa.gov.au/BelairWalls
- Email: DIT.BelairWalls@sa.gov.au