

SHEQ Flash Report

 Class 1P
 Level 1/P1
 Class 2A
 Level 2/P2
 Class 2P
 Class 1 NCR

A Flash Report must be prepared and sent to the BU SHEQ Manager within **24 hours**.

Date: 25 / 06 / 2022

Approximate Time of Incident: 1100hrs

Project: M6 Stage 1

BRIEF DETAILS OF THE INCIDENT

Incident Description:

During a compressed air service pipe relocation, a worker has tagged out both ends of the isolation points and proceeded to complete another task.

When the worker returned to continue the pipe relocation task, the worker failed to test for dead and proceeded to undo the clamp on the pipe using a rattle gun.

This released the stored energy from the pipe connection and caused the air hose to move uncontrolled across the ground until the air was depleted.

No injuries were reported.

Location:

Arncliffe, Shed B

Names of Employer/s of workers involved:

CPB Contractors Pty Ltd



IMMEDIATE ACTION TAKEN

Area secured. Work ceased. Supervisor notified. Investigation commenced.

Incident Type

Safety & Health
 Environment
 Rail Safety
 Property Damage
 Quality

Actual
 Potential

LTI
 Spill
 Discharge
 Noise

Drug and Alcohol testing undertaken?
 Yes
 No

Incident Classification: Actual: Near Hit Potential: 1P

Consequence Rating (Actual and Potential)			
	Class 1A	Class 1P	Class 2A
Safety	A Death or Permanent Disability	Had the hazard been fully realised the most probable outcome was death or permanent disability	A Medical Treatment, Restricted Work or Lost Time Injury

Name & phone number of person making this report:

Peter McInerney – Project Safety Director – Mb. 0439 209972